



**FIG. 1**  
**(Related Art)**



**FIG. 2**  
**(Related Art)**




## **FIG. 3**

### **(Related Art)**

#### ***4bits-Resolution PWM Control Signals Generator***

<b>Steps</b>	<b>PWM Control Signals (PWM Patterns)</b>	<b>Motor Speeds (RPM)</b>
<b>Step 0</b>	<b>PWM Pattern 0</b>	<b>0 (min)</b>
<b>Step 1</b>	<b>PWM Pattern 1</b>	<b>300</b>
<b>Step 2</b>	<b>PWM Pattern 2</b>	<b>600</b>
<b>Step 3</b>	<b>PWM Pattern 3</b>	<b>900</b>
<b>Step 4</b>	<b>PWM Pattern 4</b>	<b>1200</b>
⋮	⋮	⋮
<b>Step 11</b>	<b>PWM Pattern 11</b>	<b>3300</b>
<b>Step 12</b>	<b>PWM Pattern 12</b>	<b>3600</b>
<b>Step 13</b>	<b>PWM Pattern 13</b>	<b>3900</b>
<b>Step 14</b>	<b>PWM Pattern 14</b>	<b>4200</b>
<b>Step 15</b>	<b>PWM Pattern 15</b>	<b>4500 (max)</b>

# FIG. 4



# FIG. 5


## Information of Steps of 8 bits-Resolution and Motor Speeds

Steps	Motor Speeds (RPM)
Step 0	0 (min)
Step 1	18.75
Step 2	37.5
⋮	⋮
Step 176	3300
⋮	⋮
Step 187	3506.25
⋮	⋮
Step 192	3600
⋮	⋮
Step 240	4500
⋮	⋮
Step 255	4781.25 (max)


11

5


# FIG. 6




**FIG. 7**



## **FIG. 8**



## **FIG. 9**



# FIG. 10

